

API COUPLER REPAIR KIT



DATE
: 04/20/2026 02:04 PM

SKU
: 27166

BRAND
: DIXON VALVE

MODEL
: 5354K23

Features:

Poppet, bent link, link pin, link washer, 304SS cotter pin, drive link, shaft cotter pin, shaft outside washer, shaft inside washer

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Poppet Assembly replacement kit
Factory Part Number	5354K23
Used on	5300, 5300BC, 5300BCL

* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability