

5500-SERIES API COUPLER REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/08/2026 01:35 AM

SKU
: 27199

BRAND
: DIXON VALVE

MODEL
: 5500RK5

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	FKM-GFLT complete seal repair kit for 5500G
Factory Part Number	5500RK5
Weight Lb	0.5000