

**BAYLOC® DRY DISCONNECT  
COUPLER REPAIR KIT**



\* Referential image  
\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 07/09/2026 10:11 PM

SKU  
: 27477

BRAND  
: DIXON VALVE

MODEL  
: DBCX6-150RK1

Safety notes:  
WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**TECHNICAL SPECIFICATIONS**

|                            |  |
|----------------------------|--|
| <b>Includes</b>            | replacement seal kit, FFKM crank shaft O-ring, PTFE stuffing box O-ring, FFKM body O-ring, PTFE/FFKM cam gasket, PTFE O-ring |
| <b>Factory Part Number</b> | DBCX6-150RK1   |
| <b>Used on</b>             | 1-1/2" Aluminum Couplers, 1-1/2" Stainless Steel Couplers  |
| <b>Weight Lb</b>           | 0.0100   |