

## ALUMINUM BUTTERFLY VALVE REPLACEMENTS/KITS



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 04/20/2026 10:15 AM

SKU  
: 5034

BRAND  
: DIXON VALVE

MODEL  
: 5-400-422500

Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### TECHNICAL SPECIFICATIONS

<b>Description</b>	Disc Seat
<b>Factory Part Number</b>	5-400-422500
<b>Material</b>	Black Buna
<b>Used on</b>	5-400-1500
<b>Weight Lb</b>	0.7000