

API VALVE DUST CAP HANDLE REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/08/2026 11:04 AM

SKU
: 5280

BRAND
: DIXON VALVE

MODEL
: 5205-RK2

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Replacement cam arm and pin
Factory Part Number	5205-RK2
Used on	5205 API dust cap
Weight Lb	0.0800