

API COUPLER REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE

: 07/08/2026 05:11 AM

SKU

: 27165

BRAND

: DIXON VALVE

MODEL

: 5354K20

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Repair kit
Factory Part Number	5354K20
Used on	5300BC
Weight Lb	0.8710