


API COUPLER REPAIR KIT

DATE
: 07/08/2026 05:12 AM

SKU
: 27167

BRAND
: DIXON VALVE

MODEL
: 5354K25



Features:

Washer, cotter pin, handle (aluminum), shaft outside washer, clevis pin

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Aluminum handle kit replacement
Factory Part Number	5354K25
Weight Lb	1.4100

* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability