

5500-SERIES API COUPLER REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/08/2026 12:54 AM

SKU
: 27184

BRAND
: DIXON VALVE

MODEL
: 5500RK1

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	FKM-B complete seal repair kit for 5500B
Factory Part Number	5500RK1
Weight Lb	0.5000