

5500-SERIES API COUPLER REPAIR KIT



DATE
: 04/20/2026 08:01 AM

SKU
: 27192

BRAND
: DIXON VALVE

MODEL
: 5500RK17

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	FKM-GFLT seals with PTFE U-cap kit for 5500G
Factory Part Number	5500RK17

* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability