

5500-SERIES API COUPLER REPAIR KIT



DATE
: 07/08/2026 02:34 AM

SKU
: 27193

BRAND
: DIXON VALVE

MODEL
: 5500RK19

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Hi-Fluor complete seal kit for 5500H
Factory Part Number	5500RK19

* Referential image
** Some features may vary without prior notice. Sale subject to inventory availability