

## ALUMINUM BUTTERFLY VALVE REPLACEMENTS/KITS



DATE  
: 07/08/2026 03:00 AM

SKU  
: 5498

BRAND  
: DIXON VALVE

MODEL  
: 6-390-393501

Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### TECHNICAL SPECIFICATIONS

<b>Description</b>	Disc Seat
<b>Factory Part Number</b>	6-390-393501
<b>Material</b>	Black Buna
<b>Used on</b>	6-390-828U501
<b>Weight Lb</b>	1.0400

\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability