

B5101 SERIES BUTTERFLY VALVE REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE

: 04/20/2026 11:46 AM

SKU

: 8176

BRAND

: DIXON VALVE

MODEL

: B5101-RKV150

Features:

(1) seat and (2) bushings included

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Color	Brown
Factory Part Number	B5101-RKV150
Material	FKM
Size	1-1/2"
Weight Lb	0.0900