

**BAYLOC® DRY DISCONNECT  
COUPLER REPAIR KIT**



\* Referential image  
\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 04/21/2026 03:45 AM

SKU  
: 27436

BRAND  
: DIXON VALVE

MODEL  
: DBC61-150RK2

Safety notes:  
WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**TECHNICAL SPECIFICATIONS**

|                            |   |
|----------------------------|---|
| <b>Includes</b>            | replacement Buna seal cylinder, PTFE buttons and PTFE bushing (for DBC61-150) |
| <b>Factory Part Number</b> | DBC61-150RK2  |
| <b>Used on</b>             | 1-1/2" Aluminum Couplers  |
| <b>Weight Lb</b>           | 0.6000  |