

BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/08/2026 02:28 PM

SKU
: 27439

BRAND
: DIXON VALVE

MODEL
: DBC62-150RK2

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement FKM seal cylinder, PTFE buttons and PTFE bushing (for DBC62-150)
Factory Part Number	DBC62-150RK2
Used on	1-1/2" Aluminum Couplers
Weight Lb	0.1800