

## BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 04/21/2026 05:02 AM

SKU  
: 27449

BRAND  
: DIXON VALVE

MODEL  
: DBC71-150RK2

Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### TECHNICAL SPECIFICATIONS

|                            |  |
|----------------------------|--|
| <b>Includes</b>            | replacement Buna seal cylinder,<br>PTFE buttons and PTFE bushing |
| <b>Factory Part Number</b> | DBC71-150RK2   |
| <b>Used on</b>             | 1-1/2" Stainless Steel Couplers                                  |
| <b>Weight Lb</b>           | 0.4400   |