

BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT



* Referential image
** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/08/2026 03:35 PM

SKU
: 27449

BRAND
: DIXON VALVE

MODEL
: DBC71-150RK2

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement Buna seal cylinder, PTFE buttons and PTFE bushing
Factory Part Number	DBC71-150RK2
Used on	1-1/2" Stainless Steel Couplers
Weight Lb	0.4400