

**BAYLOC® DRY DISCONNECT
COUPLER REPAIR KIT**



* Referential image
** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 04/21/2026 05:02 AM

SKU
: 27463

BRAND
: DIXON VALVE

MODEL
: DBCX2-150RK1

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement seal kit, FKM crank shaft O-ring, PTFE stuffing box O-ring, FKM body O-ring, FKM cam gasket, PTFE O-ring (for DBC62-150)
Factory Part Number	DBCX2-150RK1
Used on	1-1/2" Aluminum Couplers, 1-1/2" Stainless Steel Couplers
Weight Lb	0.0400