

BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT

DATE
: 07/08/2026 03:36 PM

SKU
: 27464


BRAND
: DIXON VALVE

MODEL
: DBCX2-200RK1

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement seal kit, FKM crank shaft O-ring, PTFE stuffing box O-ring, FKM body O-ring, FKM cam gasket, PTFE O-ring
Factory Part Number	DBCX2-200RK1
Used on	2" Aluminum Couplers, 2" Stainless Steel Couplers
Weight Lb	0.0800



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability