

**BAYLOC® DRY DISCONNECT
COUPLER REPAIR KIT**



* Referential image
** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/09/2026 06:20 PM

SKU
: 27477

BRAND
: DIXON VALVE

MODEL
: DBCX6-150RK1

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement seal kit, FFKM crank shaft O-ring, PTFE stuffing box O-ring, FFKM body O-ring, PTFE/FFKM cam gasket, PTFE O-ring
Factory Part Number	DBCX6-150RK1
Used on	1-1/2" Aluminum Couplers, 1-1/2" Stainless Steel Couplers
Weight Lb	0.0100