

**BAYLOC® DRY DISCONNECT  
COUPLER REPAIR KIT**



\* Referential image  
\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 07/08/2026 04:21 PM

SKU  
: 27480

BRAND  
: DIXON VALVE

MODEL  
: DBCX7-150RK1

Safety notes:  
WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**TECHNICAL SPECIFICATIONS**

<b>Includes</b>	replacement seal kit, FFKM crank shaft O-ring, PTFE stuffing box O-ring, PTFE FKM body O-ring, PTFE/FKM cam gasket, PTFE O-ring
<b>Factory Part Number</b>	DBCX7-150RK1
<b>Used on</b>	1-1/2" Aluminum Couplers, 1-1/2" Stainless Steel Couplers
<b>Weight Lb</b>	0.0100