

BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/08/2026 05:18 PM

SKU
: 27487

BRAND
: DIXON VALVE

MODEL
: DBCXX-150RK7

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement crank shaft kit, crank shaft, cotter pin and washer
Factory Part Number	DBCXX-150RK7
Used on	1-1/2" Aluminum Couplers, 1-1/2" Stainless Steel Couplers
Weight Lb	0.3600