

**BAYLOC® DRY DISCONNECT
COUPLER REPAIR KIT**



* Referential image
** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 04/21/2026 08:15 AM

SKU
: 27487

BRAND
: DIXON VALVE

MODEL
: DBCXX-150RK7

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement crank shaft kit, crank shaft, cotter pin and washer
Factory Part Number	DBCXX-150RK7
Used on	1-1/2" Aluminum Couplers, 1-1/2" Stainless Steel Couplers
Weight Lb	0.3600