

**EZLINK® REPLACEMENT
GASKET**



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 06/14/2026 10:24 AM

SKU
: 23995

BRAND
: DIXON VALVE

MODEL
: EZL200-G-FV

Safety notes:

Take the seal out and check for any cracks, tears, nicks and make sure media is not trapped in the bellows area. If any damage to the seal, replace with a new Dixon® bellow seal that is compatible with the material that is to be conveyed.

The seal is marked with directional arrows and the word 'up' in 4 locations on the inside diameter indicating which way to insert it into the coupler. Arrows should point at you.

Warning! Only use EZLink™ seals for this coupling system. Traditional Cam & Groove gaskets, or other types of seals are not compatible and will fail.

If there is any question about which gasket to install, call Dixon® at 800-355-1991 for a recommendation.

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Material	Fluorosilicone
Factory Part Number	EZL200-G-FV
Size	2"
Weight Lb	0.0300