

**EZLINK® REPLACEMENT  
GASKET**



DATE  
: 06/14/2026 11:48 AM

SKU  
: 23998

BRAND  
: DIXON VALVE

MODEL  
: EZL300-G-FV

**Safety notes:**

Take the seal out and check for any cracks, tears, nicks and make sure media is not trapped in the bellows area. If any damage to the seal, replace with a new Dixon® bellow seal that is compatible with the material that is to be conveyed.

The seal is marked with directional arrows and the word 'up' in 4 locations on the inside diameter indicating which way to insert it into the coupler. Arrows should point at you.

Warning! Only use EZLink™ seals for this coupling system. Traditional Cam & Groove gaskets, or other types of seals are not compatible and will fail.

If there is any question about which gasket to install, call Dixon® at 800-355-1991 for a recommendation.

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**TECHNICAL SPECIFICATIONS**

<b>Material</b>	Fluorosilicone
<b>Factory Part Number</b>	EZL300-G-FV
<b>Size</b>	3"
<b>Weight Lb</b>	0.0680

\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability