

DIXON® TWO-PIECE HAMMER UNION NUT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 07/09/2026 12:49 AM

SKU
: 15747

BRAND
: DIXON VALVE

MODEL
: HU100800RN

Applications:

Replacement for damaged hammer union nuts
Used with male one-piece flange adapters

Use:

Dixon recommends using Loctite® Threadlocker Red 271™ when bolting together two-piece hammer union nuts to ensure that bolts do not loosen when in service. Bolt torque recommendation is 60 foot pounds. Option two is to weld the seams of the split nut.

Specifications:

Forged steel meets AISI standards

Features:

Lug design provides enlarged surface area to hammer
Repair nut is pinned and bolted for perfect alignment
Nut can be installed on pre-existing hammer union assembly

Construction:

Includes Bolts

Available Options:

Nut is available in other hammer union series and sizes, consult Dixon for more information.

Compatibility & Interchange Data:

Interchangeable with reliable brands

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Hammer union nut replacement
Factory Part Number	HU100800RN
Material	Forged Steel
Size	8"
Style	Figure 100
Used on	Flange adapters
Weight Lb	20.7300
Working Pressure	1000 PSI CWP