

## ALUMINUM BUTTERFLY VALVE REPLACEMENTS/KITS



\* Imágenes referenciales

\*\* Algunas características pueden variar sin previo aviso, venta sujeta a stock disponible

FECHA  
: 04/14/2026 08:40 AM

SKU  
: 2077

MARCA  
: DIXON VALVE

MODELO  
: 2-400-422237F

Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### ESPECIFICACIONES TÉCNICAS

Description	Disc
Factory Part Number	2-400-422237F
Material	Iron
Used on	2-400-1500
Weight Lb	0.3500