

API COUPLER REPAIR KIT

FECHA
: 05/10/2026 08:10 AM

SKU
: 27167

MARCA
: DIXON VALVE

MODELO
: 5354K25

Features:


Washer, cotter pin, handle (aluminum), shaft outside washer, clevis pin

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

ESPECIFICACIONES TÉCNICAS

Description	Aluminum handle kit replacement
Factory Part Number	5354K25
Weight Lb	1.4100



* Imágenes referenciales

** Algunas características pueden variar sin previo aviso, venta sujeta a stock disponible