

API COUPLER REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE

: 07/08/2026 05:12 AM

SKU

: 27163

BRAND

: DIXON VALVE

MODEL

: 5354K19

Features:

Poppet, bent link, link pin, link washer, hitch pin, drive link, shaft outside washer, shaft inside washer, shaft cotter pin

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Valve assembly repair kit
Factory Part Number	5354K19
Used on	5300, 5300B, 5300G, 5400, 5400B & 5400G API couplers
Weight Lb	0.0100