

## API COUPLER REPAIR KIT



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 04/20/2026 02:05 PM

SKU  
: 27163

BRAND  
: DIXON VALVE

MODEL  
: 5354K19

### Features:

Poppet, bent link, link pin, link washer, hitch pin, drive link, shaft outside washer, shaft inside washer, shaft cotter pin

### Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

## TECHNICAL SPECIFICATIONS

<b>Description</b>	Valve assembly repair kit
<b>Factory Part Number</b>	5354K19
<b>Used on</b>	5300, 5300B, 5300G, 5400, 5400B & 5400G API couplers
<b>Weight Lb</b>	0.0100