

## B5107-SERIES BUTTERFLY VALVE REPAIR KIT



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE

: 04/21/2026 05:28 AM

SKU

: 23121

BRAND

: DIXON VALVE

MODEL

: B5107-RKE150

Features:

(1) seat and (2) bushings included

Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### TECHNICAL SPECIFICATIONS

<b>Color</b>	Black
<b>Factory Part Number</b>	B5107-RKE150
<b>Material</b>	EPDM
<b>Size</b>	1-1/2"