

B5107-SERIES BUTTERFLY VALVE REPAIR KIT



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE

: 07/08/2026 04:38 PM

SKU

: 23138

BRAND

: DIXON VALVE

MODEL

: B5107-RKV300

Features:

(1) seat and (2) bushings included

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Color	Brown
Factory Part Number	B5107-RKV300
Material	FKM
Size	3"