

## B5107-SERIES BUTTERFLY VALVE REPAIR KIT



DATE  
: 07/08/2026 04:38 PM

SKU  
: 23139

BRAND  
: DIXON VALVE

MODEL  
: B5107-RKV400

Features:  
(1) seat and (2) bushings included

Safety notes:  
WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### TECHNICAL SPECIFICATIONS

<b>Color</b>	Brown
<b>Factory Part Number</b>	B5107-RKV400
<b>Material</b>	FKM
<b>Size</b>	4"

\* Referential image  
\*\* Some features may vary without prior notice. Sale subject to inventory availability