

## AIR RELIEF VALVE REPLACEMENT BALL

DATE

: 04/20/2026 07:17 AM

SKU

: 8711

BRAND

: DIXON VALVE

MODEL

: BARVE3T-G150

Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### TECHNICAL SPECIFICATIONS

**Factory Part Number**

BARVE3T-G150

**Material**

PTFE



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability