

## AIR RELIEF VALVE REPLACEMENT BALL

DATE  
: 07/08/2026 01:48 AM

SKU  
: 8711

BRAND  
: DIXON VALVE

MODEL  
: BARVE3T-G150

Safety notes:  
WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### TECHNICAL SPECIFICATIONS

<b>Factory Part Number</b>	BARVE3T-G150
<b>Material</b>	PTFE



\* Referential image  
\*\* Some features may vary without prior notice. Sale subject to inventory availability