

**JRZL-100 SERIES POSITIVE  
DISPLACEMENT PUMP REPAIR  
KIT**



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 05/03/2026 09:59 PM

SKU  
: 18342

BRAND  
: DIXON VALVE

MODEL  
: RZL-115B-3E-KIT

Safety notes:  
WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**TECHNICAL SPECIFICATIONS**

<b>Description</b>	Triple Lip Seal Repair Kit
<b>Includes</b>	2 - O-ring rotor EPDM, 2 - Triple Lip Seal, 2- Lip Seal Cover, 2 - Ceramic Coated Sleeve
<b>Mandatory Pkg/Box Qty</b>	1
<b>Material</b>	EPDM
<b>Factory Part Number</b>	RZL-115B-3E-KIT
<b>Used on</b>	JRZL-100 Series