

**JRZL-100 SERIES POSITIVE
DISPLACEMENT PUMP REPAIR
KIT**



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 05/03/2026 09:59 PM

SKU
: 18352

BRAND
: DIXON VALVE

MODEL
: RZL-115B-5V-KIT

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Double O-ring Seal Repair Kit
Includes	2 - O-ring, rotor FKM, 2 - O-ring, rotor case FKM, 2 - Ceramic Coated Sleeve, 2 - O-ring, Cse, Double Seal FKM, 2 - Body, Double O-ring Seal
Mandatory Pkg/Box Qty	1
Material	FKM
Factory Part Number	RZL-115B-5V-KIT
Used on	JRZL-100 Series