

**JRZL-200 SERIES POSITIVE
DISPLACEMENT PUMP REPAIR
KIT**



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 05/03/2026 11:17 PM

SKU
: 18363

BRAND
: DIXON VALVE

MODEL
: RZL-220B-3E-KIT

Safety notes:

WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Triple Lip Seal Repair Kit
Includes	2 - O-ring rotor EPDM, 2 - Triple Lip Seal, 2 - Lip Seal Cover, 2 - Ceramic Coated Sleeve
Mandatory Pkg/Box Qty	1
Material	EPDM
Factory Part Number	RZL-220B-3E-KIT
Used on	JRZL-200 Series