

**JRZL-200 SERIES POSITIVE  
DISPLACEMENT PUMP REPAIR  
KIT**



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 05/03/2026 11:17 PM

SKU  
: 18371

BRAND  
: DIXON VALVE

MODEL  
: RZL-220B-5E-KIT

Safety notes:

WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**TECHNICAL SPECIFICATIONS**

<b>Description</b>	Double O-ring Seal Repair Kit
<b>Includes</b>	2 - O-ring, rotor EPDM, 2 - O-ring, rotor case EPDM, 2 - Ceramic Coated Sleeve, 2 - O-ring, Cse, Double Seal EPDM, 2 - Body, Double O-ring Seal
<b>Mandatory Pkg/Box Qty</b>	1
<b>Material</b>	EPDM
<b>Factory Part Number</b>	RZL-220B-5E-KIT
<b>Used on</b>	JRZL-200 Series