

**JRZL-300 SERIES POSITIVE
DISPLACEMENT PUMP REPAIR
KIT**



* Referential image
** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 05/04/2026 12:49 AM

SKU
: 18384

BRAND
: DIXON VALVE

MODEL
: RZL-330B-3E-KIT

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Triple Lip Seal Repair Kit
Includes	2 - O-ring rotor EPDM, 2 - Triple Lip Seal, 2 - Lip Seal Cover, 2 - Ceramic Coated Sleeve
Mandatory Pkg/Box Qty	1
Material	EPDM
Factory Part Number	RZL-330B-3E-KIT
Used on	JRZL-300 Series