

**JRZL-400 SERIES POSITIVE
DISPLACEMENT PUMP REPAIR
KIT**



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 05/04/2026 12:53 AM

SKU
: 18397

BRAND
: DIXON VALVE

MODEL
: RZL-440B-1E-KIT

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

| | |
|------------------------------|--|
| Description | Single O-ring Seal Repair Kit |
| Includes | 2 - O-ring, rotor EPDM, 2 - O-ring, rotor case EPDM, 2 - Ceramic Coated Sleeve |
| Mandatory Pkg/Box Qty | 1 |
| Material | EPDM |
| Factory Part Number | RZL-440B-1E-KIT |
| Used on | JRZL-400 Series |