

**JRZL-400 SERIES POSITIVE  
DISPLACEMENT PUMP REPAIR  
KIT**



\* Referential image

\*\* Some features may vary without prior notice. Sale subject to inventory availability

DATE  
: 05/04/2026 02:20 AM

SKU  
: 18407

BRAND  
: DIXON VALVE

MODEL  
: RZL-440B-3V-KIT

Safety notes:  
WARNING: Cancer and Reproductive Harm- [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**TECHNICAL SPECIFICATIONS**

<b>Description</b>	Triple Lip Seal Repair Kit
<b>Includes</b>	2 - O-ring rotor FKM, 2 - Triple Lip Seal, 2 - Lip Seal Cover, 2 - Ceramic Coated Sleeve
<b>Mandatory Pkg/Box Qty</b>	1
<b>Material</b>	FKM
<b>Factory Part Number</b>	RZL-440B-3V-KIT
<b>Used on</b>	JRZL-400 Series