

**JRZL-400 SERIES POSITIVE
DISPLACEMENT PUMP REPAIR
KIT**



* Referential image

** Some features may vary without prior notice. Sale subject to inventory availability

DATE
: 05/04/2026 02:20 AM

SKU
: 18413

BRAND
: DIXON VALVE

MODEL
: RZL-440B-5E-KIT

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Double O-ring Seal Repair Kit
Includes	2 - O-ring, rotor EPDM, 2 - O-ring, rotor case EPDM, 2 - Ceramic Coated Sleeve, 2 - O-ring, Cse, Double Seal EPDM, 2 - Body, Double O-ring Seal
Mandatory Pkg/Box Qty	1
Material	EPDM
Factory Part Number	RZL-440B-5E-KIT
Used on	JRZL-400 Series